10168346

COPY

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.:	7,173,784	Docket:	HSJ920030151US1(0550)
Issue Date:	02/06/2007	Patentee:	Cideciyan, et al.

Title: APPARATUS FOR PROVIDING DATA DEPENDENT DETECTION IN A DATA READ CHANNEL

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P. O. Box 1450
Alexandria, VA 22313-1450

Certificate

APR 0 2 2007

of Correction

Sir:

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent.

☐ As some of the errors listed are due to Applicant's mistake, please charge Deposit Account No. 50-2587 (HSJ920030151US1) in the amount of $100.00 to cover the Certificate fee.

☑ As none of the errors listed are due to Applicant's mistake, no fee is necessary in connection with this Certificate.

Issuance of the Certificate of Correction should not expand or contract the scope of the claims, and re-examination should not be required.

Respectfully submitted,

CHAMBLISS, BAHNER & STOPHEL, P.C.
1000 Tallan Building
Two Union Square
Chattanooga, TN 37402
(423) 757-0264

Date: 3/26/07

David W. Lynch
No. 36,204

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page __1__ of __1__

PATENT NO.   : 7,173,784

APPLICATION NO.: 10/683,646

ISSUE DATE   : 02/06/2007

INVENTOR(S)   : Cideciyan, et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 10, Line 44: "selected sequence" should read – sequence selection stage –
Col. 10, Line 46: "selected by the processor." should read – at the output of the Viterbi decoder. --
Col. 10, Line 50: "response." should read – response at the Viterbi decoder. –
Col. 11, Line 18: "decodes" should read – decoding –
Col. 11, Line 20: "analyzes" should read –analyzing --
Col. 11, Line 21: "selects" should read – selecting –
Col. 11, Line 24: "selected sequence" should read – sequence selection stage --
Col. 11, Line 26: "selected by the signal processor." should read – at the output of the Viterbi decoder. --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Chambliss, Bahner & Stophel P.C.
1000 Tallan Bldg., Two Union Square
Chattanooga, TN 37402

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

APR 3 - 2007